

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
UTAH
29-OGCA,
2 -

Ogden Canyon Conduit
Ogden Canyon
Weber County
Utah

HAER No. UT-51

Documentation: 18 exterior photos (1987)
10 historical photos (ca. 1935)
1 photographic reproduction of construction drawing (1987)
31 data pages (1988, 1989)

John Pendlebury, Photographer, October 1987

UT-51-1 FRONT OF PINEVIEW DAM, LOOKING EAST

UT-51-2 BACK OF PINEVIEW DAM, LOOKING SOUTH, TOP OF ORIGINAL DAM APPEARS
ACROSS MIDDLE OF EARTHFILL

UT-51-3 BEGINNING OF WOOD STAVE PIPE AT 1760 FEET BELOW PINEVIEW DAM

UT-51-4 VIEW OF WOOD STAVE PIPE, LOOKING EAST

UT-51-5 ROCK RETAINING WALL FOR WOOD STAVE PIPE, LOOKING NORTH

UT-51-6 COLLAPSED AND ABANDONED SECTION OF WOOD STAVE PIPE, LOOKING WEST

UT-51-7 TUNNEL NO. 2 ENTRANCE AND AIR VALVE SHED, LOOKING WEST

UT-51-8 SUPPORT TRUSSES WITH NEW METAL PIPE, LOOKING EAST

UT-51-9 DETAIL OF BOW TRUSS STRUCTURE, LOOKING EAST

UT-51-10 TUNNEL NO. 5, INTERIOR, LOOKING EAST

UT-51-11 WOOD STAVE PIPE ON METAL CRADLE WITH WOOD CATWALK, LOOKING WEST

UT-51-12 WOOD STAVE PIPE ON WOOD CRADLE EAST OF TUNNEL NO. 7

UT-51-13 TUNNEL NO. 7, LOOKING EAST

UT-51-14 VIEW ABOVE SIPHON, LOOKING SOUTH

UT-51-15 VIEW OF SIPHON ACROSS WEBER CANYON, LOOKING EAST

UT-51-16 SURGE TANK, END OF WOOD STAVE PIPE AND BEGINNING OF CANAL
SYSTEM, LOOKING SOUTH

UT-51-17 DETAIL OF WOOD STAVE PIPE, RODS AND CONNECTION SHOES

UT-51-18 DETAIL OF WOOD REPAIR PLUG

UT-51-19 HISTORICAL PHOTO OF PINEVIEW DAM LOCATION

UT-51-20 HISTORICAL PHOTO, BEGINNING OF 75" WOOD STAVE PIPE WITH OLD
72" WOOD STAVE PIPE

UT-51-21 HISTORICAL PHOTO OF CONSTRUCTION OF WOOD STAVE PIPE

UT-51-22 HISTORICAL PHOTO OF TRESTLE AND TRUSS SUPPORT SYSTEM FOR OLD
72" WOOD STAVE PIPE

UT-51-23 HISTORICAL PHOTO OF CONSTRUCTION OF CRADLE AND TRUSSES FOR NEW
75" WOOD STAVE PIPE

UT-51-24 HISTORICAL PHOTO OF TRUSS AND RETAINING WALL FOR WOOD STAVE PIPE

UT-51-25 HISTORICAL PHOTO OF CONSTRUCTION OF SIPHON ACROSS MOUTH OF WEBER
CANYON

UT-51-26 HISTORICAL PHOTO OF DETAIL OF SIPHON ACROSS MOUTH OF WEBER CANYON

UT-51-27 HISTORICAL PHOTO OF FLOODING OF OGDEN RIVER ALONG WOOD STAVE PIPE
IN BACKGROUND

UT-51-28 HISTORICAL PHOTO OF DAMAGE TO TRUSS SUPPORT SYSTEM DUE TO EARTH
MOVEMENT

UT-51-29 ORIGINAL CONSTRUCTION DRAWING OF CRADLES AND RETAINING WALLS